

Bl
cont
A2
cont

races, the rollers are inclined, this making it difficult to so install the retainer and roller assembly.
In addition, this leads to a cause for reducing the performance (noise control or the like) of the rollers.

Page 35, paragraph 5:

A3

Note that the 6330 ball bearing is directed to one of bearings which substantially have a dimension based on the International Organization for Standardization (ISO) (for example, the 6330 ball bearing is a single row deep groove ball bearing having an inner diameter of 150mm).

IN THE CLAIMS:

Please add the following new claims 10-13:

10. (New) The retainer for roller bearings as set forth in claim 4, wherein said run out preventing portion is equal to or less than the roller effective length e and 0.75 times longer than the roller effective length c.

A4

11. (New) The retainer for roller bearings as set forth in claim 5, wherein said run out preventing portion is equal to or less than the roller effective length e and 0.75 times longer than the roller effective length c.

B

12. (New) The retainer for roller bearings as set forth in claim 8, wherein said run out preventing portion is equal to or less than the roller effective length e and 0.75 times longer than the roller effective length c.